LOCATION	VALUE		TYPE	ORIENTATION
( ) C4	.01	ufd	Disc	None
( ) C5	.047	ufd	"	"
( ) C6	.047	ufd	"	"
( ) C7	.0022	ufd	"	"
( ) C8	470	pfd	"	"
( ) C9	220	pfd	"	"
( ) C10	220	pfd	"	"
( ) C11	.01	ufd	"	"
( ) C12	.047	ufd	"	"
( ) C13	.047	ufd	"	"
( ) C14	15	ufd	Tantalum	"+" lead top

( ) Step 3. Install the following resistors in the indicated
locations. Bend leads to fit distance between mounting
holes, insert leads, pull down snug to board, solder and
trim.

LOCATION	VALUE (ohms)	COLOR CODE
( ) R1	150	brown-green-brown
( ) R2	150	" " "
( ) R3	150	" " "
( ) R4	68 K	blue-gray-orange
( ) R5	560 K	green-blue-yellow
( ) R6	33 K	orange-orange-orange
( ) R7	1 K	brown-black-red
( ) R8	1.5K	brown-green-red
( ) R9	3 K	orange-black-red
( ) R10	3 K	" " "
( ) R11	3 K	" " "
( ) R12	3 K	" " "
( ) R13	1.5K	brown-green-red
( ) R14	1.5K	" " "
( ) R15	1.5K	" " "
( ) R16	1 K	brown-black-red
( ) R17	390	orange-white-brown
( ) R18	1 K	brown-black-red
( ) R19	10	brown-black-black
( ) R20	1 K	brown-black-red
( ) R21	1 K	" " "
( ) R22	3 K	orange-black-red
( ) R23	1 K	brown-black-red
( ) R24	1 K	" " "
( ) R25	1.5K	brown-green-red
( ) R26	680	blue-gray-brown
( ) R27	33 K	orange-orange-orange
( ) R28	1.5K	brown-green-red
( ) R29	1.5K	" " "