2.1 INTRODUCTION

The Sol power supply consists of a regulator board plus additional chassis-mounted components. This section covers assembly and test of the complete power supply.

2.2 PARTS AND COMPONENTS

2.2.1 Sol Regulator (Sol-REG)

Check all parts and components against the appropriate "Parts List", Tables 2-1, 2-2 and 2-3. If you have difficulty in identifying any parts by sight, refer to Figure 3-1 on Page III-5 in Section III of this manual.

2.2.2 Power Supply Subchassis and Components

In addition to the Sol-REG, you will need the following parts and components supplied with the Sol Cabinet-Chassis Kit. Check these parts against the appropriate "Parts List(s)", Tables 6-1 and 6-2, in Section VI and separate them from the other cabinet-chassis parts.

Fan Closure Plate

Power Supply Subchassis (L-shaped)

- 4 each 4-40 x 3/16 Machine Screw
- 4 each 4-40 x 5/16 Machine Screw
- 4 each 4-40 Hex Nut
- 10 each #4 Lockwasher
- 14 each 6-32 x 1/2 Machine Screw
- 14 each 6-32 Hex Nut
- 16 each #6 Lockwasher
 - 3 each 8-32 x ½ Machine Screw
 - 3 each 8-32 Hex Nut
 - 3 each #8 Lockwasher
- ll each #6 x 1/4 Sheet Metal Screw
- 1 each #6 x 5/16 Sheet Metal Screw
- 2 each #4 Solder Lug
- 2 each 4" Spacer, 4-40 Tapped