


X-10



NOTES:

UNLESS OTHERWISE SPECIFIED:

1. ALL SCREWS ARE PART (3)
2. LABELS APPLIED TO OUTSIDE OF CHASSIS WITHIN AREA BOUNDED BY BROKEN LINE
3. INSERT (20) INTO J11 ON (2), FASTEN TO (21) ON EACH SIDE, THEN INSTALL (22) AND (23). TIGHTEN MOUNTING SCREWS ON (2) AFTER INSTALLATION IS COMPLETE.

27		SCREW, MACHINE, 4-40 x 5/16", PAN HEAD	2	2
26	101021	GUSSET, BACKPLANE, LEFT-HAND	0	1
25	102000	SOL PC CIRCUIT CARD	1	1
24		WASHER, FLAT, 1/2" O.D., 3/16" I.D., 1/16" THK	2	2
23		CARD GUIDE	-	10
22	101017	GUSSET, BACKPLANE, RIGHT HAND	-	1
21	101016	BRACKET, BACKPLANE, RIGHT ANGLE	-	2
20	103000	BACK PLANE BOARD ASSEMBLY	-	1
19		SCREW, MACHINE, 4-40 x 5/8", PAN HEAD	-	6
18		LABEL, FINGER WELL, BLACK	2	2
17		NUT, #4-40, HEX	4	4
16		LOCKWASHER, #4, INTERNAL TOOTH	3	3
15		LOCKWASHER, #6, INTERNAL TOOTH	4	4
14		SCREW, MACHINE, 4-40 x 5/16", PAN HEAD	10	16
13		SCREW, SHEET METAL, #6 x 1/4", PAN HEAD	19	31
12		SCREW, SHEET METAL, #6 x 5/16", PAN HEAD	1	1
11		SCREW, MACHINE, 6-32 x 1/2", PAN HEAD	4	4
10		" " " " 8-32 x 1" " "	2	2
9		SCREW, MACHINE, 8-32 x 1/2", PAN HEAD	8	8
8	101008	SIDE ASSEMBLY, RIGHT-HAND	1	1
7	101007	SIDE ASSEMBLY, LEFT-HAND	1	1
6	101006	BRACKET, KEYBOARD SUPPORT	2	2
5	101005	BRACKET, CONNECTING	1	1
4	103001-02	POWER SUPPLY, Sol-20	-	1
3	103001-01	POWER SUPPLY, Sol-10	1	-
2	101004	EXPANSION SUBCHASSIS	1	1
1	101003	MAIN CHASSIS	1	1

REF DES	PART OR DWG. NO.	PART DESCRIPTION	-10	-20
---------	------------------	------------------	-----	-----

ASSEMBLY, SOL

SCALE: _____ APPROVED BY: R. MARSH DRAWN BY: LITO

DATE: 01-17-77 REVISED

PROCESSOR TECHNOLOGY CORP.

DRAWING NUMBER
101000