

Sol MANUAL ERRATA SHEET #1

Reference Drawing No. 101007 in Section X (Page X-8)

The plastic tapped insert on the top edge of the left-hand masonite piece is incorrectly shown installed in the second hole from the back edge. This insert should be installed in the third hole from the back edge.

The second insert on the bottom edge is also shown incorrectly installed in the hole to the left of the center large hole. Install this insert in the hole to the immediate right of the large center hole.

ES #1